

ACCESSORIES

Remote sensor:

- 11594 SX-Alpha Remote sensor casing top cover anodized aluminum
- 11607 SX-Alpha Remote sensor ceiling bracket
- 11608 SX-Alpha Remote sensor wall bracket
- 11904 SX-Alpha Remote sensor cable with connectors 5 m
- 11905 SX-Alpha Remote sensor cable with connectors 10 m
- 11906 SX-Alpha Remote sensor cable with connectors 15 m
- 11907-[length]m SX-Alpha Remote sensor cable with connectors
- 11793 SX-Alpha Remote sensor cable without connectors (m)
- 11902 SX-Alpha Remote sensor connector kit

Alarm devices:

- 40049 E2S L101H Alarm blinker LED, 24VDC red
- 40051 E2S SONF1 Sound alarm, 24VDC 103dB
- 40054 E2S SONFL1H Combination alarm, LED 24VDC red

Signs:

- 11611 Sign GAS ALARM with warning triangle. 200 x 300 mm
- 11612 Sign GAS ALARM, 400 x 100 mm
- 11613 Sign GAS ALARM, 300 x 50 mm

Other:

- 11616 Weather cover
- 11901 SX-Alpha Remote calibration adaptor

Ask about other accessories!

SPARE PARTS

- 11872 SX-Alpha Gas detector without sensor module
- Sensor modules:
 - 11633 SX-Alpha sensor module CH₄ 0-100 %LEL
 - 11837 SX-Alpha sensor module O₂ 0-30%VOL
 - 11852 SX-Alpha sensor module C₃H₈ 0-100 %LEL
 - 11853 SX-Alpha sensor module H₂ 0-100 %LEL
 - 11854 SX-Alpha sensor module C₅H₁₂ 0-100 %LEL
 - 11855 SX-Alpha sensor module Gas:[Gas] 0-100 %LEL
 - 11868 SX-Alpha sensor module MPS 0-100 %LEL
 - 11880 SX-Alpha sensor module CO₂ 400-2000 ppm
 - 11882 SX-Alpha sensor module NH₃ 0-100 ppm
 - 11883 SX-Alpha sensor module NH₃ 0-1000 ppm
 - 11891 SX-Alpha sensor module CO 0-500 ppm
 - 11892 SX-Alpha sensor module H₂S 0-100 ppm
 - 11924 SX-Alpha sensor module CO₂ 0.04-2 %VOL
 - 11595 SX-Alpha Sensor casing sinter
 - 11624 SX-Alpha Sensor casing (with sinter and seals)
 - 11796 SX-Alpha Battery CR2025

